


SERVICE BULLETIN FOR RYOBI 30cc STRING TRIMMERS AND BRUSHCUTTERS MODEL NUMBERS RY30000, RY30000A, RY30002, RY30002A, RY30004, RY30004A, RY30021A, RY30041A, AND RY30061A



STRING TRIMMERS AND BRUSHCUTTERS FOR THE MODEL NUMBERS LISTED ABOVE WERE ORIGINALLY BUILT WITH A SLEEVE BETWEEN THE BOOM ASSEMBLY AND THE ENGINE. THE SPRING SHOWN IN THIS SERVICE BULLETIN REPLACED THE SLEEVE AND IS CURRENTLY BEING USED. IF YOUR STRING TRIMMER OR BRUSHCUTTER WAS BUILT WITH A SLEEVE, REPLACE IT WITH THE SPRING PROVIDED IN THIS KIT.

983000652
11-09-04 (REV:00)